

INSTALLATION INSTRUCTIONS

102035 Fuel Injector Harness – 1984-1985 turbo Buick 3.8

This replacement injector harness has been manufactured to OEM specifications for perfect fit. All connectors, wire and hardware are factory GM parts, ensuring long reliable life of the product.



1984-1985 VIN 9

