

INSTALLATION INSTRUCTIONS

102050 Battery Negative Cable – 1989 turbo Trans-Am

Factory replacement battery negative cable fits correctly for your turbo Trans-Am application. All critical lug connections are crimped and soldered to ensure reliability. Also includes center harness support clamp.

This cable attaches to the turbo support bracket and includes a short pigtail which must be securely attached to the inner fender well ground bolt. This assures proper chassis grounding. Be sure all attachment points are securely tightened.

